











8109




8109N

NR	ELEMENT	8109N
E1		1
E2		1
E3		1
E4		1
E5		1
E6		1

NR	ELEMENT	8109N
E7		1
E8		1






8109N

Nr	Element	DIN	ELEMENT	Σ
1		-	S6x60	2
2		-	W6x60	1
21		DIN 125	8x16	1
77		-	K3_d30_A89_G	1
90		DIN 125	16x30	12
164		DIN 985	M16	6
213		-	Z_NA_1	1
214		-	Z_NA_2	1
229		-	Z_R_42	12
230		-	S1_8100_0	6
231		-	S2_8100_0	6



8109N



8109N



ENG: „Due to the irregular shapes of natural robinia wood trunks, all dimensions provided in the documentation may slightly vary from the actual dimensions of the product.”

PL: "Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu."




1

8109N




2

8109N




INST_81_0_1




3

8109N



INST_81_0_1



4

8109N

B25 0,54m³

min. 48H

