






















8163






8163N


NR	ELEMENT	8163N
E1	<div data-bbox="237 566 391 600">D8163_1N</div> 	1
E2	<div data-bbox="231 887 386 920">D8163_2N</div> 	1
E3	<div data-bbox="231 1202 386 1236">D8163_3N</div> 	1
E4	<div data-bbox="231 1518 386 1552">D8163_4N</div> 	1
E5	<div data-bbox="242 1821 399 1854">D8163_5N</div> 	1
E6	<div data-bbox="231 2150 386 2184">D8163_6N</div> 	1

NR	ELEMENT	8163N
E7	 <p>D8163_7N</p>	1
E8		1
E9		 <p>1</p>
E10		2
E11		1
E12		1


NR	ELEMENT	8163N
E13		1
E14		1
E15		1
E16		1
E17		1
E18		1

NR	ELEMENT	8163N
E19		1
E20		1
E21		1

# 8163N






PL: "Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu."



1


8163N






2

8163N




INST\_81\_87  
INST\_81\_16  
INST\_81\_63  
INST\_81\_2




3

8163N




INST\_81\_89  
INST\_81\_89G




4

8163N



INST\_81\_124  
INST\_81\_17A  
INST\_81\_164



5

8163N

3

B25 0,9m

min. 48H

